

Declassification Review by NGA/DoD

OUT56718

S E C R E T 172037Z

1965 SEP 17 20 48Z

25X1

1. CAMERA B 23 WAS USED IN MISSION 8043 FLOWN ON 15 SEPTEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A WAVERING PLUS DENSITY STREAK IS PRESENT INTERMITTENTLY WITHIN THE MISSION. EXAMPLES ARE LOCATED IN FRAMES 244 AND 347. THERE IS A HEAT SPLICE BETWEEN FRAMES 967/968. ANOTHER HEAT SPLICE IS LOCATED IN FRAME 1144 ACCOMPANIED BY PROCESSING STREAKS AND IRREGULAR PLUS DENSITY STREAKS. A MANUFACTURING SPLICE IS LOCATED IN FRAME 354.

C. 9L SIDE: WAVERING PLUS DENSITY STREAKS OCCUR INTERMITTENTLY THROUGHOUT THE MISSION NEAR THE INBOARD EDGE. EXAMPLES ARE ON FRAMES 18, 582/583, 708, 882, 1094 TO 1099, 1718 AND 2113. EMULSION DIGS ARE NOTED ON FRAMES 624, 634, 641, 645, 667 AND 672. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 47/48, 109/110, 1184/1185, 1251/1252, 2164/2165 AND THROUGH FRAME 1160.

D. BOTH SIDES: EDGE FOG AND EDGE STATIC OCCURS ALONG BOTH EDGES THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT ALONG BOTH EDGES. THE LAST TITLED FRAME IS 2216.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

20 SEP 1965

COPIES RECEIVED		
Cy No.	Office	Act.
	File	
	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD ICB	
3,4	TID	✓
	PID	
	PAC	
	DIAXX 4	
	SPAD	
	NSA LO	
	DIA AP	

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

-2-

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED OR OBSCURED 5 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--

1